



| REFERENCIA  | PASSO | ISO     | W  | H  | K  | h   | A    | C    | CALHA  | Kg/m  |
|-------------|-------|---------|----|----|----|-----|------|------|--------|-------|
| LA - 77     | 3/8"  | 06 - B2 | 20 | 10 | 15 | 1.5 | 5.4  | 20   | C 2010 | 0.615 |
| LA - 78     | 1/2"  | 08 - B2 | 20 | 15 | 17 | 2.2 | 7.5  | 21.4 | C 2010 | 0.240 |
| LA - 79     | 5/8"  | 10 - B2 | 20 | 15 | 17 | 2.6 | 9.3  | 25.7 | C 2812 | 0.260 |
| LA - 80     | 3/4"  | 12 - B2 | 28 | 15 | 20 | 2.4 | 11.3 | 30.7 | C 2812 | 0.330 |
| LA - 80 - A | 1"    | 16 - B2 | 38 | 15 | 27 | 3.5 | 16.5 | 48.0 | C 3818 | 0.650 |
| LA - 80 - B | 1" ¼  | 20 - B2 | 38 | 15 | 30 | 4.3 | 19.0 | 55.0 | C 3818 | 0.925 |
| LA - 80 - C | 1" ½  | 24 - B2 | 38 | 15 | 35 | 5.5 | 24.7 | 72.0 | C 3818 | 1.425 |